

GPR Summary Report

2024-09-10

Scott Sutton



This report is created using a Sensors & Software EKKQ_Project software template. All content, interpretations, conclusions and recommendations are created by the user and Sensors & Software is not responsible for the reliability or veracity of the contents in this report. Project Name:10767Survey Date:2024-09-04Report Date:2024-09-10Client:Municipality of St. CharlesSite Description:Municipal Cemetary

Additional Comments: Columbarum





Figure 1 Layer identified at approx 1.0m depth.





Conclusions:

No target anomolies were identified in the surveyed area for the installation of the Columbarum.

This report is created using a Sensors & Software EKKQ_Project software template. All content, interpretations, conclusions and recommendations are created by the user and Sensors & Software is not responsible for the reliability or veracity of the contents in this report.